



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Sep 2021, 17:43:41
Transaction Number	43202090 (CC10006)	Queue Number	312309



Chassis Number	6T1BE42K09X581097
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Corolla
Model Year	2009
Color	White
Mileage	0 N/A

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	REAR BACK PANEL, BUMPER FRAME REPAIRED & BEND	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.I Other	FRONT FENDER FRAME, BUMPER FRAME, RADITOR SUPPORT REPAIRED	اخرى
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE END REPAIRED	الشاسيه
03 Engine Condition		المحرك
03.A Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	MINOR OIL LEAK	الجير

DEFECT	REMARKS	
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020/2017 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2017/2019 CRACKED	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	OK	اخرى
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Other	OK	اخرى
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED	ازرع
11 Steering Condition		المقود
11.A Steering Boot	BOOT CUT & LEAKING	ربلة المقود
11.B Steering Oil	POWER STEERING LEAKING	زيت المقود
12 Interior Condition		الاجزاء الداخلية
12.A Other	OK	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.