





### Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18780848	Plate Category	: PRIVATE
Transaction Date	: 18 DEC 2019 09:34:01	Plate Number	: 0347 EA
Queue Number	: 126316	Import Doc. Ref.	:
Chassis Number	: 1N4AL2A94AC150347	Manufacturer/Model	: NISSAN/ALTIMA
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.05 - Steering Coupling, Column		ثنائي توصيلة المقود
02.08 - Power Steering Pump		المضخة الهيدرولكية للمقود
02.16 - Engine Mounting		كراسي المحرك
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.02 - Paint		الصبغ
05.03 - Doors		الابواب
05.05 - Bumpers		الدعامية
06 General Items		الاشياء العامة
06.04 - Horn		الزامور
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.25 - Body Repainted		أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.



### Test Certificate

Site Number	:	840-TASJEEL EM AUCTION	Plate Code	:	0
Transaction Number	:	18780848	Plate Category	:	PRIVATE
Transaction Date	:	18 DEC 2019 09:34:01	Plate Number	:	0347 EA
Queue Number	:	126316	Import Doc. Ref.	:	
Chassis Number	:	1N4AL2A94AC150347	Manufacturer/Model	:	NISSAN/ALTIMA
Engine Number	:		Model Year	:	2010
Vehicle Class	:	LIGHT VEHICLE	Vehicle Color	:	BLACK
Service / Indicator	:	DSC AUCTION			

Statement of Vehicle Condition