

Queue Number

2855827

Transaction Date

10 Oct 2026, 12:46:15

Site Name

840 - Emirates Auctions

Transaction Number

15901092 (CC10013) (CC10025)



Vehicle Details

Chassis Number	1FA6P8TH8J*****
Specification	Imported
Make	Ford
Model	Mustang
Model Year	2018
Color	White
Mileage	284033 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING RUSTY	الصبغ
01.C Doors	LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED MINOR DENT	الارضية
01.F Bumper	MISSING	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Trunk	REFITTED MISALIGN	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME REPAIRED , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS OUTER MINOR DENT / CHECK VISIBLE AREA ONLY / OK	الشاسية
02.B Chassis Number	DOOR POST STICKER FADED NOT VISIBLE TO CHECK PROPERLY	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------------	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 WORN OUT EXPIRED	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2022 , RIGHT SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES / NUT MISSING	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنايير الفرامل
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX CRACK , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
08.B AC Condition	OK	المكيف
08.C Sun Visor	LEFT SIDE BRACKET DAMAGED , RIGHT SIDE MISSING	حاجب الشمس
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae