



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>27 Dec 2021, 18:06:52</b>
Transaction Number	<b>90993538 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JNKCV61E0AM650371</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Infiniti</b>
Model	<b>G 37</b>
Model Year	<b>2010</b>
Color	<b>Red</b>
Mileage	<b>186423 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY TOTALY,REPAINTED,PORTION REPAIRED,DENTS, SCRATCHES	الصبغ
01.B Fenders	FRONT & REAR BOTH SIDE REPAINTED , PORTION REPAIRED	مدكار
01.C Doors	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED & REAR BOTH SIDE REPAINTED,RIGHT SIDE PORTION REPAIRED	أبواب
01.D Bonnet	REPAINTED,SHOCK STAND WEAK	غطاء المحرك
01.E Roof	REPAINTED	السقف
01.F Trunk	REPAINTED	صندوق
01.G Floor	RIGHT SIDE RUNNING BOARD REPAIRED	الارضية
01.H Bumper	REPAINTED	دعامية
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Dash Board	DASH BOARD CRACKED	لوحة القيادة
02.B Mirror	BOTH SIDE FOLDING NOT WORKING	المرايا
02.C Steering Wheel and control buttons	MINOR WORN OUT & HARD	عجلة القيادة وازرار التحكم
02.D AC Condition	OK	المكيف
02.E Door Panel	FRONT LEFT SIDE PORTION WORN OUT	لوحة بطانة الباب

DEFECT	REMARKS	
<b>03 Wipers and Arms</b>		<b>المساحات</b>
03.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
03.B Other	WATER TANK CAP MISSING	اخرى
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2016 CRACKED , EXPIRED	الاطار الامامي
04.B Rear Tyre	LEFT SIDE 2017 MINOR CRACKED & RIGHT SIDE 2016 CRACKED,EXPIRED	الاطار الخلفي
04.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Tie Rod End	BOOT CUT	مؤخرة الروداد
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Engine Condition	MINOR OIL LEAK	حالة المحرك
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box	OK	الجير
<b>08 Battery Condition</b>		<b>حالة البطارية</b>
08.A Battery bracket	BATTERY BRACKET MISSING	حامل البطارية
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	FRONT LEFT SIDE CHASSIS MINOR BEND &REAR RIGHT SIDE JOINT AREAR REPAIRED,MINOR BEND	الشاسيه
<b>10 Seats Condition</b>		<b>المقاعد</b>
10.A Seat Belt	FRONT RIGHT SIDE NOT WORKING	حزام الأمان
10.B Seat Condition	OK	حالة المقاعد
<b>11 Brake Condition</b>		<b>الفرامل</b>
11.A Hand Brake	WEAK	فرامل اليد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	--
Chassis No :	JNKCV61E0AM650371
Vehicle Make :	INFINITI
Vehicle Model :	G
Vehicle Class :	Light Vehicle
Body Type :	LOCOMOTIVE
Fuel :	Benzene
Color :	Red
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	186425 Kms.
Origin :	Japan
Model Year :	2010
Gear Type :	Automatic
Engine Size :	5600 CC
Engine No :	VQ3718039...
Horse Power :	328
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	2000 Kgs.
Empty Weight :	1500 Kgs.

Certificate Number :	5-TAS-2022-15850020
Inspection Date :	09-01-2022
Certificate Print Date :	09-01-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	15 min 38 sec
Appointment Ref Number :	--
Start Time :	15:50
End Time :	16:06
Lane :	03
Token No. :	205
Attempt :	2
Prints No :	1

## Inspection Findings

Defects	Issue	Severity
Park and Tail lamps <b>REPAIR FRONT RIGHT SIDE PARK LIGHT</b>	Defective	Major
Engine <b>REPAIR ENGINE OIL LEAK</b>	Oil leaking continuously	Major
Front Seat belts <b>CHANGE FRONT RIGHT SIDE SEAT BELT DAMAGE</b>	Defective	Major

Discrepancies	Old Value	New Value	Verified
Description - Registration Incorrect Vehicle Description	LOCOMOTIVE	SALOON	
Engine Size Discrepancy in Engine Size	5600	3700	

## Inspection Remarks:

FRONT LEFT SIDE&REAR RIGHT SIDE OUTER &VIN NUMBER AREA MINOR DENT/FLOOR MINOR DENT/ GEAR OIL PAN/ RIGHT SIDE RUNNING BOARD DENT/ FRONT&REAR BUMPER REPAIRED

## Payment Details

Inspection Performed by 62439	Payment Method Cash	Transaction Number 15850020	Service Fees AED 70 Collected on 09/01/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

