CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2990275
Transaction Date	14 Nov 2026, 11:46:41
Site Name	840 - Emirates Auctions
Transaction Number	68834452 (CC10013) (CC10011)



Vehicle Details

Chassis Number	KL1PM5D50E*******
Specification	GCC Specification
Make	Chevrolet
Model	Cruze
Model Year	2014
Color	Brown
Mileage	217635 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REFITTED,LEFT SIDE DEEP DENT	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED MINOR DENT	الارضية
01.E Bumper	MISALIGN PORTION CRACK,TOWING HOOK COVER MISSING, LOGO FADED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION RUST PROOFED DIRTY MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED,BRACKET DAMAGED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	SIGN OF LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
09.B Mirror	CENTER FADED	المرايا
09.C AC Condition	OK,GRILL PORTION DAMAGED,SWITCH NOT WORKING PROPERLY LOOSE	المكيف
09.D Dash Board	PORTION LOOSE	لوحة القياده
09.E Sun Visor	RIGHT SIDE MIRROR COVER MISSING	حاجب الشمس
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09.G Engine Start Button	STARTING PROBLEM	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae