

Queue Number

2814952

Transaction Date

30 Sep 2026, 16:14:20

Site Name

840 - Emirates Auctions

Transaction Number

56485120 (CC10009) (CC10012)



## Vehicle Details

|                   |                   |
|-------------------|-------------------|
| Chassis Number    | SALWA2EF6G*****   |
| Specification     | GCC Specification |
| Make              | Range Rover       |
| Model             | Sport             |
| Model Year        | 2016              |
| Color             | Black             |
| Mileage           | 98085 Km          |
| Fuel Type         | Petrol            |
| Transmission Type |                   |
| No. Of Cylinders  | 8                 |

## Condition

## Remarks

## الحالة

## 01 Body

## جسم المركبة

|              |                                                                     |             |
|--------------|---------------------------------------------------------------------|-------------|
| 01.A Fenders | FRONT BOTH SIDE REFITTED,RIGHT SIDE BOTH REPAINTED PORTION REPAIRED | مدكار       |
| 01.B Paint   | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES        | الصبغ       |
| 01.C Doors   | RIGHT SIDE BOTH REPAINTED PORTION REPAIRED                          | أبواب       |
| 01.D Rusty   | UNDER BODY PARTS GETTING RUSTY                                      | صدأ         |
| 01.E Rusty   | UNDER BODY PARTS GETTING RUSTY                                      | صدأ         |
| 01.F Floor   | FLOOR CHASSIS NOT VISIBLE                                           | الارضية     |
| 01.G Bumper  | MISALIGN                                                            | دعامية      |
| 01.H Bonnet  | REPAINTED,REFITTED                                                  | غطاء المحرك |
| 01.I Trunk   | MISALIGN,AUTO NOT WORKING                                           | صندوق       |

## 02 Chassis Condition

## الشاسي

|                     |                                                                              |             |
|---------------------|------------------------------------------------------------------------------|-------------|
| 02.A Chassis        | CHASSIS COMPLETELY COVERED MUDDY CHECKED VISIBLE AREA ONLY/OK                | الشاسيه     |
| 02.B Other          | MAKE STEAM WASH & REMOVE ALL UNDER FLOOR CHASSIS COVERS FOR RECHECK PROPERLY | اخرى        |
| 02.C Chassis Number | CHECKED ONLY ON STICKER                                                      | رقم القاعدة |

## 03 Engine Condition

## المحرك

|                              |                                       |
|------------------------------|---------------------------------------|
| 03.A Engine Visual Condition | OIL LEAK REFITTED GETTING RUSTY MUDDY |
|------------------------------|---------------------------------------|

الحالة النظرية للمحرك

## 04 Transmission Condition

## الجير

| Condition                          | Remarks                                                       | الحالة                 |
|------------------------------------|---------------------------------------------------------------|------------------------|
| 04.A Gear Box Visual Condition     | REFITTED OIL WET GETTING RUSTY                                | الحالة النظرية للجير   |
| 04.B Road Test                     | NOT CHECKED                                                   | فحص علي الطريق         |
| <b>05 Tires and Rims Condition</b> |                                                               | <b>الاطارات</b>        |
| 05.A Front Tyre                    | BOTH SIDE 2024                                                | الاطار الامامي         |
| 05.B Rear Tyre                     | BOTH SIDE 2024                                                | الاطار الخلفي          |
| 05.C Rims Condition                | MINOR DENT SCRATCHES                                          | حالة الجنوط            |
| <b>06 Lights</b>                   |                                                               | <b>الاضاءة</b>         |
| 06.A Head Light                    | LEFT SIDE BRACKET DAMAGED REPAIRED,RIGHT SIDE PORTION DAMAGED | الاضاءة الرئيسية       |
| 06.B Tail Light                    | RIGHT SIDE FADED                                              | الضوء الخلفي           |
| 06.C Warning Light                 | WARNING LIGHT ON DISPLAY                                      | ضوء تحذير              |
| <b>07 Suspension System</b>        |                                                               | <b>ممتص الصدمات</b>    |
| 07.A Arms                          | BUSHES CRACKED                                                | ازرع                   |
| 07.B Other                         | SUSPENSION REFITTED                                           | اخرى                   |
| <b>08 Interior Condition</b>       |                                                               | <b>الحالة الداخليه</b> |
| 08.A Other                         | INTERIOR PARTS GETTING RUSTY                                  | اخرى                   |
| 08.B Mirror                        | LEFT SIDE COVER CRACK                                         | المرآيا                |
| 08.C AC Condition                  | NOT WORKING PROPERLY                                          | المكيف                 |
| 08.D Dash Board                    | PORTION DAMAGED                                               | لوحة القيادة           |
| 08.E Roof Ceiling                  | RIGHT SIDE BOTH GRAB HANDLE MISSING                           | بطانة السقف            |
| 08.F Door Panel                    | RIGHT SIDE SPEAKER COVER PORTION CRACK                        | لوحة بطانة الباب       |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](https://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](https://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

للشكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)