



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>14 Jan 2022, 11:56:25</b>
Transaction Number	<b>93917865 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN8AY2NY9D9055026</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Patrol</b>
Model Year	<b>2013</b>
Color	<b>White</b>
Mileage	<b>232299 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHE.PORTION PAINT DAMAGED,PORTION GETTING RUSTY,PORTION FADED	الصبغ
01.C Doors	LEFT SIDE BOTH DOOR REPAIRED,REPAINTED & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING MINOR RUSTY	صدأ
01.E Bonnet	MISALIGN	غطاء المحرك
01.F Bumper	REPAINTED	دعامية
01.G Roof	REPAINTED,PORTION PAINT DAMAGED,GETTING RUSTY	السقف
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A Mirror	VIEW MIRROR MINOR LOOSE	المرابا
02.B Sun Visor	GLASS COVER LOOSE	حاجب الشمس
02.C AC Condition	OK	المكيف
02.D Other	GEAR SHIFTING LEVER KNOB LOOSE	اخرى
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>

DEFECT	REMARKS	
03.A Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
03.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
<b>04 Wipers and Arms</b>		<b>المساحات</b>
04.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Gear Box	REFITTED	الجير
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Engine Condition	REFITTED,SHAKING	حالة المحرك
06.B Mount	BUSHES MINOR CRACKED	كرسي
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	OK	الشاسيه
<b>08 Brake Condition</b>		<b>الفرامل</b>
08.A Break Pads	GETTING WEAR	سفايف الرامل
08.B Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
<b>09 Seats Condition</b>		<b>المقاعد</b>
09.A Seat Belt	OK	حزام الأمان
09.B Seat Condition	SEATS HAVE EXTRA COVER & FRONT RIGHT SIDE SEAT ADJUSTMENT BUTTON DAMAGED	حالة المقاعد
<b>10 Lights</b>		<b>الاضاءة</b>
10.A Head Light	LENS FADED	الاضاءة الرئيسية
10.B Other	ALL LIGHT WORKING	اخرى
<b>11 Battery Condition</b>		<b>حالة البطارية</b>
11.A Battery Condition	OK	حالة البطارية
<b>12 Suspension System</b>		<b>ممتص الصدمات</b>
12.A Shock Absorber	REAR RIGHT SIDE SHOCK ABSORBER MINOR OIL LEAK	ممتص الصدمات
<b>13 Steering Condition</b>		<b>المقود</b>
13.A Steering Oil	MINOR OIL LEAK	زيت المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.