

Queue Number

2919564

Transaction Date

29 Oct 2026, 13:23:16

Site Name

840 - Emirates Auctions

Transaction Number

44258650 (CC10009) (CC10012)



Vehicle Details

Chassis Number

WA1DFAFS1E*****

Specification

GCC Specification

Make

Audi

Model

Q3

Model Year

2014

Color

Brown

Mileage

128104 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONT BOTH SIDE REPAINTED PORTION REPAIRED

مدكار

01.B Paint

BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES

الصبغ

01.C Doors

FRONT LEFT SIDE REPAINTED

أبواب

01.D Rusty

UNDER BODY PARTS GETTING RUSTY

صدأ

01.E Floor

CENTER FLOOR FRONT CHASSIS FULLY COVERED MUDDY

الارضية

01.F Bonnet

REPAINTED PORTION REPAIRED , SHOCK WEAK

غطاء المحرك

01.G Trunk

AUTO , SHOCK WEAK NOT WORKING

صندوق

02 Chassis Condition

الشاسي

02.A Chassis

FRONT CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK

الشاسيه

03 Engine Condition

المحرك

03.A Engine Visual Condition

OIL LEAK PARTS REFITTED SHAKING

الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition

MINOR OILLEAK PARTS REFITTED

الحالة النظرية للجير

04.B Road Test

NOT CHECKED

فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre

BOTH SIDE 2025

الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LEFT SIDE NOT WORKING	الاضاءة الرئيسية
06.B Warning Light	WARNING MESSAGES ON IN DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	INNER PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK , REAR RIGHT SIDE GRILL DAMAGED	المكيف
08.C Power Window Switch And Glass	REAR BOTH SIDE NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
08.D Audio	EXTRA SCREEN	صوتيات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae