

Queue Number 2862726

Transaction Date 14 Oct 2026, 16:54:31

Site Name
840 - Emirates AuctionsTransaction Number
24019143 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WAURGBFD5D*****
Specification	GCC Specification
Make	Audi
Model	A8
Model Year	2013
Color	White
Mileage	107701 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	MINOR DENT SCRATCHES ON BODY	الصبغ
01.B Doors	REAR BOTH SIDE REFITTED	أبواب
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED CHECK VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN SCRATCHES, CHROME STRIP PORTION CRACK	دعامية
01.F Windshield	REAR CURTAIN MISSING	زجاج
01.G Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
01.H Door Handle & Lock	REAR LEFT SIDE DOOR AUTO CLOSE NOT WORKING	مقابض الأبواب والأقفال
01.I Vehicle Color	WHITE / BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT BOTH SEAT BACK COVER LOOSE PORTION DAMAGED	حالة المقاعد
---------------------	--	--------------

05 Exhaust System

نظام العادم

Condition	Remarks	الحالة
05.A Other	TAIL PIPE CUT REWELDED	اخرى
06 Transmission Condition		الاجير
06.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظره للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Tail Light	LEFT SIDE PORTION CRACKED	الضوء الخلفي
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOE BOX COVER WORN OUT,REAR CIGARETTE LIGHTER PANEL COVER FADED	اخرى
10.B Mirror	ADJUSTMENT SWITCH WORN OUT	المرايا
10.C AC Condition	OK	المكيف
10.D Roof Light	FRONT PANEL MINOR LOOSE	أنارة السقف
10.E Audio	SCREEN AUTO NOT WORKING,PANEL PORTION WORN OUT	صوتيات
10.F Roof Ceiling	PORTION MINOR LOOSE	بطانه السقف
10.G Door Panel	PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Sunroof	NOT WORKING PROPERLY,REAR CURTAIN STUCK	فتحت سقف
10.J Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae