CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2922802 |
| Transaction Date | 30 Oct 2026, 14:53:26 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 85510562 (CC10009) (CC10012) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | SALWA2EF6G******* |
| Specification | GCC Specification |
| Make | Range Rover |
| Model | Sport |
| Model Year | 2016 |
| Color | Red |
| Mileage | 141615 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 8 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Fenders | FRONT BOTH SIDE REFITTED | مدكار |
| 01.B Paint | BODY MINOR DENT SCRATCHES , PORTION PROTECTION STICKER | الصبغ |
| 01.C Doors | REFITTED | أبواب |
| 01.D Rusty | UNDER BODY PARTS GETTING RUSTY | صدأ |
| 01.E Floor | FLOOR CHASSIS NOT VISIBLE | الارضية |
| 01.F Bumper | MISALIGN | دعامية |
| 01.G Roof | PORTION PROTECTION STICKER | السقف |
| 01.H Bonnet | REFITTED | غطاء المحرك |
| 01.I Vehicle Color | RED / BLACK | لون المركبة |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK | الشاسيه |
| 02.B Other | REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY | اخري |
| 02.C Chassis Number | LAMINITED CHECKED ON STICKER ONLY | رقم القاعدة |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | MINOR OIL LEAK PARTS REFITTED GETTING RUSTY | الحالة النظريه للمحرك |
| **04 Exhaust System** | | نظام العادم |
| 04.A Other | DENT, TAILPIPE CUT REWELDED | اخري |

| Condition | Remarks | الحالة |
|---|---|---|
| **05 Transmission Condition** | | الجير |
| 05.A Gear Box Visual Condition | PARTS REFITTED OIL WET | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |
| 06.A Front Tyre | LEFT SIDE 2022 , RIGHT SIDE 2023 | الاطار الامامي |
| 06.B Rear Tyre | LEFT SIDE 2023 , RIGHT SIDE 2022 | الاطار الخلفي |
| **07 Lights** | | الاضاءة |
| 07.A Tail Light | LEFT SIDE MINOR CRACK | الضوء الخلفي |
| **08 Interior Condition** | | الحاله الداخليه |
| 08.A Other | INTERIOR PARTS REFITTED ,PARTS GETTING RUSTY | اخري |
| 08.B AC Condition | OK , REAR RIGHT SIDE ROOF GRILL LOW BLOWER NOT COOLING | المكيف |
| 08.C Sun Visor | BOTH SIDE MIRROR LIGHT NOT WORKING | حاجب الشمس |
| 08.D Sunroof | SUNROOF CURTAIN WHILE OPENING LOOSE | فتحت سقف |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**