

Queue Number 2793389

Transaction Date 24 Sep 2026, 16:40:49

Site Name
840 - Emirates AuctionsTransaction Number
73562460 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WP1ZZZ92ZG*****
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2016
Color	Brown
Mileage	159200 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE SKIRT PORTION DAMAGED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPLETELY MUDDY PORTION DENT	الارضية
01.E Bumper	REAR RIGHT SIDE REFLECTOR CRACKED	دعامية
01.F Bonnet	SHOCK WEAK NOT WORK	غطاء المحرك
01.G Fuel Tank	COVER PORTION WORN OUT	خزان الوقود
01.H Vehicle Color	GOLDEN	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY MUDDY OILY NOT VISIBLE PROPERLY, CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	FOR RECHECK PROPERLY MAKE BODY LEVEL UP STEAM WASH REMOVE ALL UNDER COVERS	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED OIL PARTS REFITTED, GETTING RUSTY MUDDY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT SIDE COVER PORTION DAMAGED	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED PARTS REFITTED, GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED ,	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	LEATHER LOOSE	لوحة القيادة
09.D Roof Ceiling	REFITTED	بطانه السقف
09.E Door Panel	PORTION LOOSE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae