



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **17 May 2023, 11:57:47**  
 Transaction Number **59981164 (CC10013)** Queue Number **718833**



Chassis Number **MR0CW6CD3G0030697**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Toyota**  
 Model **Hilux**  
 Model Year **2016**  
 Color **White**  
 Mileage **552361 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.B AC Condition	OK	المكيف
01.C Dash Board	LEFT SIDE TEA CUP HOLDER NOT CLOSE	لوحة القيادة
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Tail Light	LEFT SIDE DAMAGED	الانارة
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Seat Condition	PORTION CUT	حالة المقاعد
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Bumper	MISALIGN MINOR DENT	دعامية
05.B Paint	BODY PORTION REPAINTED PORTION REPAIRED & MINOR DENT ,SCRATCHES	الصبغ

DEFECT	REMARKS	
05.C Floor	UNDER FLOOR PORTION GETTING RUSTY	الارضية
05.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2021 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACKED	الاطار الخلفي
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	OIL WET	حالة المحرك النظري
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Shock Absorber	FRONT LEAK WEAK	ممتص الصدمات
08.B Arms	LOWER ARM BUSH CRACK	ازرع
08.C Leaf Spring	BUSH CRACK	
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	CHASSIS FRAME GETTING RUSTY & MUDDY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.