CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2937796
Transaction Date	02 Nov 2026, 16:52:37
Site Name	840 - Emirates Auctions
Transaction Number	57834151 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WP1AE2922D*******
Specification	Imported
Make	Porsche
Model	Cayenne
Model Year	2013
Color	Black
Mileage	79159 Km
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES (BODY SHAPE CHANGE OLD TO NEW MODEL)	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED MUDDY DIRTY FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER COVER FOR RECHECK CHASSIS	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REFITTED,MISALIGN	غطاء المحرك
01.H Trunk	REFITTED,INNER COVER PART MISSING,FRONT SWITCH NOT WORKING PROPERLY	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	DOOR POST STICKER NOT VISIBLE / CHECK ONLY WINDSHIELD STICKER	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Exhaust System		**نظام العادم**
04.A Modification	SYSTEM MODIFIED	تعديلات

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	GEAR FAULT , DELAY SHIFTING , MINOR JERKING , REFITTED , PARTS GETTING RUSTY (REVERSE NOT SHIFTING PROPERLY)	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
05.C Four Wheel Drive	NOT ENGEGED PROPERLY	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Indicator & Hazard light	REAR BOTH SIDE INDICATOR NOT WORKING PROPERLY REPOSITION	الاشارات
07.B Warning Light	WARNINF LIGHTS ON DISPLAY	ضوء تحذير
07.C Revers Light	NOT WORKING	نور الرجوع للخلف
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Other	SUSPENSION PARTS MUDDY DIRTY	اخري
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR MODIFIED REFITTED GETTING RUSTY	اخري
09.B AC Condition	OK	المكيف
09.C Power Window Switch And Glass	MAIN SWITCH PANEL LOOSE,FRONT RIGHT SIDE SWITCH NOT WORKING LOOSE	مفتاح النافذه و الزجاج
09.D Dash Board	PORTION WORN OUT LOOSE	لوحة القياده
09.E Roof Ceiling	PORTION LOOSE	بطانه السقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae