



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	30 Dec 2021, 17:51:12
Transaction Number	42066386 (CC10006)	Queue Number	312309



Chassis Number	JTMHU09J5B5053706
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	2011
Color	Antique white
Mileage	146252 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Wipers and Arms		المساحات
01.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
02 Body		جسم المركبة
02.A Paint	BODY TOTALLY REPAINTED & PORTION REPAIRED	الصبغ
02.B Pillars	RIGHT SIDE PILLAR OUTER REPAIRED	القوائم
02.C Trunk	REPAINTED,REFITTED	صندوق
02.D Bonnet	REPAINTED,PORTION REPAIRED , REFITTED	غطاء المحرك
02.E Fenders	FRONT & REAR BOTH SIDE REPAINTED , REAR BOTH SIDE PORTION REPAIRED	مدكار
02.F Doors	FRONT & REAR BOTH SIDE REPAINTED , FRONT LEFT SIDE PORTION REPAIRED	أبواب
02.G Roof	REPAINTED	السقف
02.H Bumper	REPAINTED	دعامية
03 Interior Condition		الحالة الداخليه
03.A Floor Matting	REPLACED	فرش الأرضيه
03.B AC Condition	OK & AC GRILL ADJUSTMENT BUTTON MISSING	المكيف
03.C Steering Wheel and control buttons	MINOR WORN OUT & HORN NOT WORKING	عجلة القيادة وازرار التحكم

DEFECT	REMARKS	
03.D Other	BRAKE PADEL RUBBER MISSING	اخرى
04 Engine Condition		المحرك
04.A Other	UPPER ENGINE COVER MISSING	اخرى
04.B Engine Condition	REFITTED,SIGN OF OIL WET	حالة المحرك
05 Transmission Condition		الجير
05.A Gear Box	REFITTED & SIGN OF OIL WET	الجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Steering Condition		المقود
06.A Steering Oil	OIL LEAK	زيت المقود
06.B Other	STEERING WHEEL HARD	اخرى
07 Suspension System		ممتص الصدمات
07.A Arms	FRONT BOTH SIDE LOWER ARM BUSH CRACKED	ازرع
08 Exhaust System		نظام العادم
08.A Other	EXHAUST BRACKET RUBBER CRACKED & PIPE REWELDED	اخرى
09 Seats Condition		المقاعد
09.A Seat Condition	MIDDLE LEFT SIDE SEAT DAMAGED	حالة المقاعد
09.B Seat Belt	OK	حزام الأمان
10 Lights		الاضاءة
10.A Indicator & Hazard light	FRONT LEFT SIDE DOOR INDICATOR LIGHT COVER DAMAGED	الاشارات
10.B Revers Light	NOT WORKING	نور الرجوع للخلف
11 Chassis Condition		الشاسي
11.A Chassis	OK&GETTING MINOR RUSTY PORTION	الشاسيه
12 Battery Condition		حالة البطارية
12.A Battery Condition	OK	حالة البطارية
13 Tires and Rims Condition		الاطارات
13.A Front Tyre	BOTH SIDE 2019 MINOR CRACKED	الاطار الامامي
13.B Rear Tyre	BOTH SIDE 2019 MINOR CRACKED	الاطار الخلفي
13.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.