CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3028113
Transaction Date	23 Nov 2026, 16:46:03
Site Name	840 - Emirates Auctions
Transaction Number	51713485 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WP122292ZG*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2016
Color	Black
Mileage	114270 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED RIGHT PORTION REPAINTED & REAR BOTH SIDE PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED,RIGHT SIDE BOTH REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED DIRTY OILY	الارضية
01.F Trunk	NOT OPEN	صندوق
01.G Door Handle &Lock	REAR LEFT SIDE DOOR OUTER HANDLE LOOSE,REAR RIGHT SIDE AUTO NOT CLOSE	مقابض الأبواب والأقفال
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	CORRECT VIN NUMBER (WP1ZZZ92ZGKA09309)	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Other	UPPER COVER PART MISSING	اخري
03.C Engine Visual Condition	OIL LEAK DRIPPING , COMPONENTS REFITTED , PARTS GETTING RUSTY OILU MUDDY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR JERKING , OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY OILY	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Wipers and Arms		**المساحات**
06.A Other	BOTTLE CAP MISSING	اخري
07 Lights		**الاضاءة**
07.A Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
08 Suspension System		**ممتص الصدمات**
08.A Shock Absorber	SIGN OF LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
08.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		**الحاله الداخليه**
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	OK,REAR RIGHT SIDE NO COOLING	المكيف
09.C Dash Board	LEATHER PORTION LOOSE	لوحة القياده
09.D Roof Ceiling	LOOSE	بطانه السقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae