CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2959224
Transaction Date	09 Nov 2026, 13:03:25
Site Name	840 - Emirates Auctions
Transaction Number	11554749 (CC10009) (CC10019)



Vehicle Details

Chassis Number	JN8AY25Y3C*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2012
Color	Grey
Mileage	133519 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION RUSTY,PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR MUDDY OILY PORTION DENT	الارضية
01.D Bumper	MISALIGN,PORTION CRACKED	دعامية
01.E Bonnet	REFITTED,SHOCK NOT WORKING	غطاء المحرك
01.F Trunk	AUTO SWITCH NOT WORKING PROPERLY	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY PORTION MINOR DENT/OK	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	OIL LEAK OPEN REFITTED SHAKING GETTING RUSTY MUDDY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT PORTION LOOSE	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK REFITTED MUDDY RUSTY MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Tail Light	RIGHT SIDE MINOR DAMAGED	الضوء الخلفي
08 Interior Condition		**الحاله الداخليه**
08.A Other	INETRIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
08.B Mirror	LEFT SIDE FOLDING NOT WORKING & CENTER MIRROR PORTION LOOSE	المرايا
08.C AC Condition	OK	المكيف
08.D Audio	SCREEN PORTION FADED	صوتيات
08.E Dash Board	LEATHER REPLACED.PORTION LOOSE	لوحة القياده
08.F Sun Visor	RIGHT SIDE LIGHT MIRROR NOT WORKING	حاجب الشمس
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	GEAR LOCK COVER MISSING ,KNOB WORN OUT	ذراع نقل السرعات
08.I Engine Start Button	SWITCH PORTION LOOSE	زر تشغيل المحرك
09 Battery Condition		**حالة البطارية**
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae