CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2970569
Transaction Date	10 Nov 2026, 11:54:00
Site Name	840 - Emirates Auctions
Transaction Number	88188785 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KL8CB6SA5M*******
Specification	Imported
Make	Chevrolet
Model	Spark
Model Year	2021
Color	--
Mileage	71531 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED,LEFT SIDE REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES .	الصبغ
01.C Doors	FRONT LEFT SIDE REPAIRED REPAINTED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT .	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAIRED REPAINTED REFITTED .	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Vehicle Color	PIEGE	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASISI END ,OUTER SKIRT MINOR DENT ,CHASISS COVERED ,CHECKED ONLY VISIBLE AREA .	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL PAN MINOR DENT COMPONENT PARTS GETTING RIUSTY,SHAKING	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	OIL PAN MINOR DENT COMPONENT PARTS GETTING RIUSTY,GET SHAKING	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED,	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2023.	الاطار الامامي
05.B Rear Tyre	RIGHT SIDE 2020 EXPIRED CRACKED. LEFT SDE 2024 CRACKED .	الاطار الخلفي
05.C Spare Tire &Tools	MISSING.	الاطار الاحتياطي و العدة
06 Lights		**الاضاءة**
06.A Head Light	LENS GETTING FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		**الفرامل**
07.A Brake Pedal	SPONGY.	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		**ممتص الصدمات**
08.A Shock Absorber	MINOR LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Interior Condition		**الحاله الداخليه**
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
09.B AC Condition	OK	المكيف
09.C Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.D Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae