



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 Jan 2023, 11:48:24</b>
Transaction Number	<b>28719422 (CC10009)</b>	Queue Number	<b>657962</b>



Chassis Number	<b>WDCBB7CBXBA748528</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>ML 500</b>
Model Year	<b>2011</b>
Color	<b>Black</b>
Mileage	<b>90056 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Rear Tyre	BOTH SIDE 2019,	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2022	الاطار الامامي
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Sunroof	NOT WORKING	فتحت سقف
02.B AC Condition	OK	المكيف
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Sign of front accident		وجود مؤشر لحادث في المقدمة
03.B Sign of side accident		وجود مؤشر لحادث في الجانب
03.C Floor	UNDER FLOOR FENDER CHASSIS COVERED CHECKED VISIBLE AREA ONLY	الارضيه
03.D Door Handle & Lock	LEFT SIDE BOTH / RIGHT SIDE REAR SENSOR RUBBER MISSING	مقابض الأبواب والأقفال
03.E Doors	RIGHT BOTH SIDE REPAINTED, PORTION REPAIRED	أبواب
03.F Fenders	FRONT BOTH SIDE REPAINTED, PORTION REPAIRED REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
03.G Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT, SCRATCHES	الصبغ

DEFECT	REMARKS	
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Other	STABILIZER LINK BOOT CUT	اخرى
04.B Ball Joint	BOOT CUT	مفصل كروي
04.C Shock Absorber	REAR LEAK	ممتص الصدمات
04.D Arms	LOWER ARM BUSHES CRACKED	ازرع
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Axle	REAR BOOT CUT	اكسلات
05.B Tie Rod End	BOOT CUT	مؤخرة الروداد
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Mount	MOUNT RUBBER CRACKED	كرسي
06.B Smoke	MINOR WHITE SMOKE	دخان
06.C Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
07.B Road Test	NOT CHECK	فحص علي الطريق
07.C Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	CHASSIS CHECKED VISIBLE AREA ONLY/OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.