

Queue Number 2766184

Transaction Date 17 Sep 2026, 14:45:45

Site Name
840 - Emirates AuctionsTransaction Number
68862820 (CC10013) (CC10013)

Vehicle Details

Chassis Number MRHGD66555*****
 Specification GCC Specification
 Make Honda
 Model City
 Model Year 2005
 Color Black
 Mileage 270867 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED, DENTS, SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK	دعامية
01.E Fuel Tank	DENT	خزان الوقود
01.F Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	REAR EXTENSION REPAIRED DENT PORTION RUSTY / FRONT BOTH SIDE LOADING POINT RUSTY WEAK BULGED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION WORN OUT CRACK	حالة المقاعد
---------------------	------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2025 BOTH SIDE	الاطار الامامي
06.B Rear Tyre	2022 DRY CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنائير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CUT	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	CENTER VIEW MIRROR FADED	المرآيا
10.C AC Condition	NOT CHECKED	المكيف
10.D Dash Board	GETTING FADED PORTION WORN OUT	لوحة القيادة
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae