CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2999097 |
| Transaction Date | 17 Nov 2026, 14:40:37 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 50169146 (CC10013) (CC10011) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | 5J6RW6890K******* |
| Specification | GCC Specification |
| Make | Honda |
| Model | CRV |
| Model Year | 2019 |
| Color | Grey |
| Mileage | 116980 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Fenders | FRONT RIGHT SIDE STRIP PORTION WORN OUT | مدكار |
| 01.B Paint | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES | الصبغ |
| 01.C Doors | RIGHT SIDE BOTH REPAINTED PORTION REPAIRED | أبواب |
| 01.D Rusty | UNDER FLOOR SUSPENSION PARTS GETTING RUSTY | صدأ |
| 01.E Floor | UNDER FLOOR PORTION COVERED | الارضية |
| 01.F Bumper | SCRATCHES | دعامية |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | COMPONENTS REFITTED , PARTS GETTING RUST Y | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | الجير |
| 04.A Gear Box Visual Condition | MINOR JERKING , PARTS GETTING RUSTY | الحالة النظريه للجير |
| 04.B Road Test | NOT CHECKED | فحص علي الطريق |
| **05 Tires and Rims Condition** | | الاطارات |
| 05.A Front Tyre | BOTH SIDE 2022 GETTING WORN OUT | الاطار الامامي |
| 05.B Rear Tyre | BOTH SIDE 2022 DRY CRACK | الاطار الخلفي |

| Condition | Remarks | الحالة |
|---|---|---|
| **06 Suspension System** | | ممتص الصدمات |
| 06.A Arms | ARM BUSHES DRY CRACK | ازرع |
| **07 Interior Condition** | | الحاله الداخليه |
| 07.A Other | INTERIOR PARTS GETTING RUSTY | اخري |
| 07.B AC Condition | OK | المكيف |
| 07.C Sun Visor | LEFT SIDE MINOR LOOSE | حاجب الشمس |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**