

Queue Number

2585372

Transaction Date

28 Jul 2026, 15:52:53

Site Name

840 - Emirates Auctions

Transaction Number

83045029 (CC10006) (CC10019)



Vehicle Details

Chassis Number

JN8AY2NY2G*****

Specification

GCC Specification

Make

Nissan

Model

Patrol

Model Year

2016

Color

White

Mileage

291085 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED, PORTION REPAIRED,REFITTED & REAR RIGHT SIDE PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED, PORTION REPAIRED,	أبواب
01.D Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.E Bonnet	SHOCK WEAK,REPAINTED, PORTION REPAIRED,REFITTED	غطاء المحرك
01.F Other	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED	اخرى
01.G Trunk	REPAINTED & SWITCH BUTTON DAMAGED	صندوق
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS ,BODY MOUNT REPAIRED, CHASSIS FRAME GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CUT	كرسي
03.B Engine Visual Condition	SHAKING,ABNORMAL NOISY,OVERHEAT,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	JERKING, REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Gear Box Mount	BUSH CRACKED	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
05.D Four Wheel Drive	4WD STACKING,REFITTED,WARNING LIGHT ON INDISPLAY,	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 WORN OUT	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Steering Box	OIL LEAK	جهاز المقود
09.B Tie Rod End	BOOT CUT	مؤخرة الروداد
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
10.B Mirror	CENTER MIRROR PORTION LOOSE	المرآيا
10.C AC Condition	OK	المكيف
10.D Dash Board	PORTION MELTED	لوحة القيادة
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	HARD, WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae