



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 21 Jul 2022, 14:56:48 |
| Transaction Number | 87611612 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | JN8AY2NYOD9057778 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Patrol |
| Model Year | 2013 |
| Color | Grey |
| Mileage | 178662 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|---|------------------------|
| 01 Body | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES | الصبغ |
| 01.B Bonnet | PORTION REPAIRED,REPAINTED | غطاء المحرك |
| 01.C Trunk | PORTION REPAIRED,REPAINTED | صندوق |
| 01.D Floor | UNDER FLOOR PARTS THICKRUST PROOFED | الارضية |
| 01.E Fenders | PORTION REPAIRED,REPAINTED | مدكار |
| 01.F Doors | REAR BOTH SIDE & FRONT LEFT SIDE PORTION REPAIRED,REPAINTED,FRONT RIGHT SIDE REPAIRED,REPAINTED | أبواب |
| 02 Transmission Condition | | الجير |
| 02.A Road Test | NOT CHECK | فحص علي الطريق |
| 02.B Gear Box Mount | MOUNT RUBBER CRACKED | كرسي الجير |
| 02.C Visual Gear Box Condition | OK | حالة الجير النظرى |
| 03 Interior Condition | | الحاله الداخليه |
| 03.A AC Condition | LOW COOLING | المكيف |
| 04 Tires and Rims Condition | | الاطارات |

| DEFECT | REMARKS | |
|------------------------------|---------------------------------------|---------------------|
| 04.A Front Tyre | BOTH SIDE 2021 | الاطار الامامي |
| 04.B Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |
| 05 Seats Condition | | المقاعد |
| 05.A Seat Condition | SEATS HAVE EXTRA COVER | حالة المقاعد |
| 06 Engine Condition | | المحرك |
| 06.A Visual Engine Condition | OK | حالة المحرك النظري |
| 07 Chassis Condition | | الشاسي |
| 07.A Chassis | CHASSIS FRAME THICK RUST PROOFED , OK | الشاسيه |
| 08 Suspension System | | ممتص الصدمات |
| 08.A Arms | LOWER ARM BUSHES CRACKED | ازرع |
| 08.B Ball Joint | BOOT CUT | مفصل كروي |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.