



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Jan 2022, 18:15:01
Transaction Number	42675654 (CC10006)	Queue Number	312309



Chassis Number	KMHDG41C8FU372566
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Elantra
Model Year	2015
Color	White
Mileage	117315 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Steering Condition		المقود
01.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
02 Suspension System		ممتص الصدمات
02.A Arms	FRONT LOWER ARM BUSH MINOR CRACKED	ازرع
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2019	الاطار الامامي
03.C Rims Condition	RIMS GETTING RUSTY	حالة الجنوط
04 Wipers and Arms		المساحات
04.A Wiper Arm & Blade	LEFT SIDE BLADE MISSING & WORN OUT	ازرع المساحات والشفرات
05 Interior Condition		الحالة الداخليه
05.A Mirror	CENTER MIRROR LOOSE	المرايا
05.B AC Condition	OK & FRONT GRILL ADJUSTMENT LOCK MISSING	المكيف
06 Body		جسم المركبة
06.A Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
06.B Sign of back accident		وجود مؤشر لحادث في الخلف
06.C Bumper	FRONT BUMPER LOGO LOOSE	دعامية
06.D Roof	PORTION RUSTY	السقف
06.E Fenders	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED & FRONT BOTH SIDE REFITTED	مدكار
06.F Doors	RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	أبواب
06.G Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
06.H Trunk	REPAINTED,REFITTED	صندوق
06.I Paint	BODY PORTION REPAINTED,PORTION REPAIRED, MINOR DENT,SCRATCHES , PORTION RUSTY	الصبغ
06.J Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
06.K Floor	BACK PANEL ,QUATER PANEL REPAIRED	الارضية
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	FRONT BOTH SIDE &REAR LEFT SIDE PARK LIGHT NOT WORKING	الانارة
07.C Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
08 Battery Condition		حالة البطارية
08.A Battery Condition	OK	حالة البطارية
09 Chassis Condition		الشاسي
09.A Chassis Extension	REAR RIGHT SIDE CHASSIS EXTENSION REPAIRED	تمديدات الشاسي
09.B Chassis	OK	الشاسيه
10 Seats Condition		المقاعد
10.A Seat Belt	OK	حزام الأمان
10.B Seat Condition	SEATS HAVE EXTRA COVER & FRONT SEATS HAVE MINOR HOLE	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.