



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	05 Jan 2022, 17:45:32
Transaction Number	24955015 (CC10006)	Queue Number	312309



Chassis Number	1GTN29EC1FZ155006
Engine Number	
Vehicle Class	Heavy
Manufacturer	GMC
Model	Sierra
Model Year	2015
Color	Brown
Mileage	91843 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE PORTION REPAINTED & RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,	الصبغ
01.C Doors	RIGHT SIDE REPAINTED,PORTION REPAIRED & RIGHT SIDE OUTER DOOR PILLAR REPAINTED,PORTION REPAIRED	أبواب
01.D Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.E Other	REAR CARRIOR BOX REPAINTED,PORTION REPAIRED	اخرى
02 Seats Condition		المقاعد
02.A Seat Belt	OK	حزام الأمان
02.B Seat Condition	OK	حالة المقاعد
03 Wipers and Arms		المساحات
03.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
03.B Other	WATER TANK CAP MISSING	اخرى
04 Interior Condition		الحاله الداخليه
04.A AC Condition	NOT WORKING	المكيف

DEFECT	REMARKS	
04.B Dash Board	EXTRA SWITCH FIXED IN DASHBAORD	لوحة القيادة
05 Battery Condition حالة البطارية		
05.A Battery Condition	OK	حالة البطارية
06 Tires and Rims Condition الاطارات		
06.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019 MINOR CRACKED	الاطار الخلفي
06.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
07 Exhaust System نظام العادم		
07.A Modification	CATAYLIC CONVERTER MISSING &EXHAUST PIPE REWELDED	تعديلات
08 Transmission Condition الجير		
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OK	الجير
09 Suspension System ممتص الصدمات		
09.A Other	FRONT STABILIZER LINK BUSHES MISSING	اخرى
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Engine Condition المحرك		
10.A Engine Condition	MINOR OIL LEAK	حالة المحرك
10.B Other	ENGINE AIR FILTER MODIFIED	اخرى
11 Chassis Condition الشاسي		
11.A Chassis	OK	الشاسيه
12 Lights الاضاءة		
12.A Head Light	ALL LIGHT WORKING	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.