

TEST CERTIFICATE

Site Number Transaction Number

06.A Visual Engine Condition

840-Emirates Auctions 82909268 (CC10006)

Transaction Date

31 Jul 2022, 14:25:41

Queue Number

312309



Vehicle Class Car

Manufacturer Mercedes

Model Model Year

Color

Mileage Fuel Type

No. Of Cylinders

Specification

WDF44770513363251

V 250

2017

Black

5440 Km

Diesel

European Imported

حالة المحرك النظرى

DEFECT	REMARKS
DEFECT	KEIVIAKKS

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2019	الاطار الامامي
02 Body		جسم المركبة
02.A Floor	UNDER FLOOR PORTION COVER	الارضية
02.B Paint	MINOR DENTS, SCRATCHES ON BODY	الصبغ
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	ОК	حالة الجير النظرى
04 Interior Condition		الحاله الداخليه
04.A AC Condition	ОК	المكيف
05 Chassis Condition		الشاصي
05.A Chassis	VISIBLE AREA OK	الشاسيه
06 Engine Condition		المحرك

ОК

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.