CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966531
Transaction Date	10 Nov 2026, 11:53:34
Site Name	840 - Emirates Auctions
Transaction Number	97705721 (CC10009) (CC10011)



Vehicle Details

Chassis Number	LFPH4ACP4P*******
Specification	GCC Specification
Make	HONGQI
Model	H5
Model Year	2023
Color	Gold
Mileage	69172 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY PORTION REPAIRED REPAINTED,MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS FULLY COVERED	الارضية
01.D Bumper	MISALIGN PORTION CRACKED SCRATCHES,RIGHT SIDE REFLECTOR DAMAGED	دعامية
01.E Windshield	DAMAGED	زجاج
01.F Trunk	REPAINTED PORTION REPAIRED,HANDLE MISSING	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD REFITTED LEFT SIDE LOWER BAR CRACKED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK PARTS REFTTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	COVER PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 GETTING WORN OUT CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED	اخري
09 Interior Condition		الحاله الداخليه
09.A AC Condition	OK	المكيف
09.B Power Window Switch And Glass	FRONT BOTH SIDE SWITCH LOOSE	مفتاح النافذه و الزجاج
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10 Battery Condition		حالة البطارية
10.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae