



# Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

DSC AUCTION

Transaction Number : 21596260 Plate Category : PRIVATE

Transaction Date : 11 OCT 2020 16:36:04 Plate Number : 19693 EA

Queue Number : 231431

Chassis Number : WDDSJ4FB5JN619693 Manufacturer/Model : MERCEDES/CLA 220

Engine Number :

Service / Indicator

Model Year : 2018
Vehicle Color : WHITE

Import Doc. Ref.

Vehicle Class : LIGHT VEHICLE

Statement of Vehicle Condition

| Defect                                   | Result | Remarks  |                              |
|--|--------|--|------------------------------|
| AUTOMATIC TEST:                          |        |  |                              |
| 13 Brake System                          |        |  | الفر امل                     |
| 13.04 - Brake Test                       | Passed |  | فحص الفرامل                  |
| 14 Exhaust Gas Test                      |        |  | الغاز العادم والكربون        |
| 14.01 - Exhaust Gas Test                 | Passed |  | فحص الغاز العادم-الكربون     |
| VISUAL TEST:                             |        |  |                              |
| 02 Steering And Suspension System        |        |  | عجلة القيادة ونظام التوصيلات |
| 02.15 - Suspension Crack Or Bend, Bushes |        | SUSPENSION SUBFRAME REPAIRED/<br>REFITTED / SUSPENSION REFITTED    | التويصلات                    |
| 04 Tires Rims                            |        |  | الاطارات والعجلات            |
| 04.01 - Front Left And Right Hands Tires |        | ALL TIRES DOT 2017   | الاطارات الامامية            |
| 04.07 - Rims                             |        | MINOR SCRATCHES  | الرنجات                      |
| 05 Body                                  |        |  | الهيكل                       |
| 05.02 - Paint                            |        | BODY SCRATCHES & DENTS / PAINT<br>THICKNESS FROM 80 TO 150 MICRONS | الصبغ                        |
| 05.05 - Bumpers                          |        | REFITTED   | الدعامية                     |
| 05.08 - Chassis (Frame)                  |        | FRONT BOTH SIDE MEMBER ENDS DENTS                                  | الشاصية                      |
| 06 General Items                         |        |  | الاشياء العامة               |
| 06.14 - Transmission Condition           |        | ОК   | حالة ناقل الحركة             |
| 06.16 - Engine Condition, Smoke          |        | ENGINE REFITTED  | حالة المحرك - الدخان         |
| 07 Remarks                               |        |  | ملاحظات                      |
| 07.04 - Others                           |        | 19154 KMS  | ملاحظات اخرى                 |
| 09 Auction                               |        |  | الفحص الكامل                 |
| 09.02 - Need Wheel Alignment             |        |  | بحاجة الى ميزانية العجلات    |
| 09.14 - Sign Of Front Accident           |        |  | أثر حادث في مقدمة المركبة    |

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص نظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية

# **Test Certificate**









Possession Certificate: 64668785 WDDSJ4FB5JN619693 Chassis No: Vehicle Make: MERCEDES Vehicle Model: CLA220D Vehicle Class: Light Vehicle **Body Type:** SALOON Fuel: Benzene Color: White **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 19156 Kms. Origin: Model Year: 2018 **Engine Size:** Gear Type: 2000 CC Engine No: NIL **Horse Power:** Cylinders: Axles No: No Of Doors: 4 No Of Seats: G. V. W.: Empty Weight: 1300 Kgs.

Certificate Number: 5-TAS-2020-12758073 Inspection Date: 14-10-2020 Certificate Print Date : 14-10-2020 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Emirates Auction Total Time Taken: 6 min 58 sec Appointment Ref Number: --Start Time: 10:12 End Time: 10:19 Lane: Token No.: 1 Attempt: Prints No: 1

#### Carbon footprint

1850 Kas.



Thank you! You are environment protector

#### Estimated Vehicle Consumption (Rate in 12 Months)



3831 KM

Distance per

year

273 L Fuel consumed per year

1



vear



### **Parameter Readings**

Service brake imbalance on front axle

12 %

Service brake imbalance on rear axle 0%

Parking brake imbalance between LHS and RHS

Vehicle on Petrol CO Reading 0%

Reading 14 PPM VOL

Vehicle on Petrol HC

Inspection Remarks: FRONT BOTH SIDE MEMBER ENDS DENTS

### **Payment Details**

**Inspection Performed by** 59460

**Parking Slot No** 

**Payment Method** VTP Credit Account **Service Name Registration Test** 

Transaction Number 12758073 **Attempt** 

**Service Fees** AED 170 Collected on 14/10/2020 Received by

Raul Canceran Galang

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. 🚺 هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السّير و المرور 21ُ لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995