CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2983278
Transaction Date	17 Nov 2026, 14:28:22
Site Name	840 - Emirates Auctions
Transaction Number	35242985 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WBS1H9100H*******
Specification	Imported
Make	BMW
Model	M2
Model Year	2017
Color	Grey
Mileage	64811 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED REFITTED,REAR RIGHT PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING FADED	الصبغ
01.C Doors	RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED FLOOR PORTION & RUNNING BOARD REPAIRED	الارضية
01.F Floor	UNDER FLOOR COVERED DIRTY MUDDY FLOOR PORTION & RUNNING BOARD REPAIRED	الارضية
01.G Bumper	MINOR SCRATCHES	دعامية
01.H Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.I Pillars	RIGHT SIDE A/PILLAR OUTER PANEL REPAIRED	القوائم
01.J Trunk	REFITTED,SWITCH MELTED	صندوق
01.K Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HAED INNER FENDER FRAME REPAIRED ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.L Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED SUSPECT REPLACED	الشاسيه
02.B Chassis Number	VIN FRAME REPAIRED	رقم القاعدة

Condition	Remarks	الحالة
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	REAR CHILD SEAT LOCK DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	NUT MISSING	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	GETTING LEAK	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A AC Condition	OK	المكيف
09.B Power Window Switch And Glass	RIGHT SIDE SWITCH NOT WORKING	مفتاح النافذه و الزجاج
09.C Engine Start Button	SMART KEY MISSING	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae