

Queue Number 2796620

Transaction Date 25 Sep 2026, 16:42:39

Site Name
840 - Emirates AuctionsTransaction Number
49629098 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WBA2C11090*****
Specification	Imported
Make	BMW
Model	218
Model Year	2015
Color	White
Mileage	215558 Km
Fuel Type	Diesel
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	REAR LEFT SIDE PORTION DENT	مدكار
01.B Paint	BODY PORTION REPAINTED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR COMPLETELY COVERED MUDDY NOT VISIBLE	الارضية
01.F Bumper	PORTION DAMAGED	دعامية

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COMPLETELY MUDDY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH & REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخرى
02.C Chassis Number	STICKER MISSING	رقم القاعدة

03 Engine Condition المحرك

03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY MUDDY, MINOR SHAKING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	FRONT BOTH SIDE BACK SIDE STAND MISSING	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	PARTS REFITTED, MUDDY GETTING RUSTY	الحالة النظرية للجير
--------------------------------	-------------------------------------	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	RIGHT SIDE PORTION LOOSE	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CUT	الزرع
09 Steering Condition		المقود
09.A Steering Boot	BOOT CUT	ربلة المقود
09.B Axle	BOOT CUT	اكسلات
10 Interior Condition		الحالة الداخليه
10.A AC Condition	OK	المكيف
10.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae