



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>05 Jul 2022, 12:18:49</b>
Transaction Number	<b>93563274 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN6BE6DS6F9012132</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Nissan</b>
Model	<b>NV350</b>
Model Year	<b>2015</b>
Color	<b>White</b>
Mileage	<b>147087 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	OIL LEAK,SHAKING,REFITTED	حالة المحرك النظري
01.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Bonnet	REPAIRED,REPAINTED	غطاء المحرك
02.B Sign of front accident		وجود مؤشر لحادث في المقدمة
02.C Sign of back accident		وجود مؤشر لحادث في الخلف
02.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHE	الصبغ
02.E Fenders	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
02.F Trunk	PORTION REPAIRED,REPAINTED	صندوق
02.G Other	FRONT BUMPER FRAME BULK HEAD RIGHT SIDE WHEEL ARCH , BACK PANEL CROSS MEMBER REPAIRED	اخرى
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Other	STABILIZER LINK BOOT CUT	اخرى
03.B Arms	CONTROL ARM BUSHES CRACKED	ازرع
03.C Ball Joint	BOOT CUT	مفصل كروي

DEFECT	REMARKS	
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Steering Wheel and control buttons	WORN OUT & HORN NOT WORKING	عجلة القيادة وازرار التحكم
04.B AC Condition	AIR FLOW LOW & NOT COOLING	المكيف
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
05.B Head Light	BOTH SIDE PARK LIGHT,LOW BEAM & RIGHT SIDE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
06.B Front Tyre	LEFT SIDE 2010 CRACKED,EXPIRED & RIGHT SIDE 2018 CRACKED	الاطار الامامي
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
07.B Road Test	NOT CHECK	فحص علي الطريق
<b>08 Chassis Condition</b>		<b>الشاصي</b>
08.A Chassis	OK	الشاسيه
<b>09 Seats Condition</b>		<b>المقاعد</b>
09.A Seat Condition	PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.