

Queue Number

2849678

Transaction Date

09 Oct 2026, 16:37:19

Site Name

840 - Emirates Auctions

Transaction Number

39529128 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JTHBE26238*****
Specification	Imported
Make	Lexus
Model	IS 350
Model Year	2008
Color	Black
Mileage	145094 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED POTION REPAIRED (OLD SHAPE CHANGE TO NEW MODEL) DENT SCRATCHES PORTION FADED , GETTING RUSTY	الصبغ
01.C Doors	BOTH LEFT SIDE REFITTED	أبواب
01.D Floor	UNDER FLOOR , RUNNING BOARD DENT , MUDDY	الارضية
01.E Bumper	MISALIGN , DAMAGE FIX BY SCREW , REAR LOGO MISSING	دعامية
01.F Roof	REPAINTED PORTION REPAIRED	السقف
01.G Bonnet	REPAINTED PORTION REPAIRED , MISALIGN , REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE A/B PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	NOT OPENING	صندوق
01.J Sign of front accident	BUPMER FRAME , INNDER FENDER FRAME , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS END LOWER DENT , COVERED CHECK VISIBLE AREA ONLY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NO START , ALL SYSTEM NOT CHECK , GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DAMAGE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST PIPECUT REWELDED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	GETTING RUSTY , OIL LEAK DRIPPING	الحالة النظرية للجير
06.B Propeller Shaft	FLANGE DRY CRACK	ناقل الحركة
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 , WORN OUT CRACK , RIGHT SIE BOLT MISSING	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2019 CRACK EXPIRED	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES , CENTER HUB COVER MISSING	حالة الجنوط
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	WATER RESERVIOR TANK MISSING	ازرع المساحات والشفرات
09 Lights		الاضاءة
09.A Head Light	LENS GETTING FADED , ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
10 Brake Condition		الفرامل
10.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
11 Interior Condition		الحالة الداخلية
11.A Other	CENTER CONSOLE BOX DAMAGE , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
11.B Mirror	CENTER VIEW MIRROR DAMAGE , RIGHT SIDE VIEW MIRROR LOOSE	المرايا
11.C AC Condition	NOT CHECK , VENT GRILL GETTING FADED	المكيف
11.D Floor Matting	DIRTY	فرش الأرضيه
11.E Audio	CONTROL BUTTON DAMAGE	صوتيات
11.F Dash Board	DAMAGE , MELTED	لوحة القيادة
11.G Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.H Odometer reading	CLUSTER PORTION FADED	قراءة عداد المسافات
11.I Door Panel	PORTION LOOSE , DAMAGE	لوحة بطانة الباب
11.J Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
11.K Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير

station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae