CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906072
Transaction Date	26 Oct 2026, 15:54:58
Site Name	840 - Emirates Auctions
Transaction Number	40983339 (CC10010) (CC10011)



Vehicle Details

Chassis Number	JN1CC11C26*******
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2006
Color	Silver
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	LEFT SIDE BOTH NOT OPEN,FRONT LEFT SIDE OUTER LOCK HANDLE MISSING	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,FRONT DAMAGED	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED DENT ,REAR BOTH SIDE EXTENSION END DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK.	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK	المكيف
11.C Dash Board	PORTION CRACK,FUES BOX COVER MISSING	لوحة القياده
11.D Roof Ceiling	PORTION LOOSE	بطانه السقف
11.E Sun Visor	LEFT SIDE MODIFIED LOOSE	حاجب الشمس
11.F Odometer reading	NOT CHECK	قراءة عداد المسافات
11.G Door Panel	PORTION DAMAGED	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT,PANEL PORTION DAMAGED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae