

Queue Number 2788274

Transaction Date 23 Sep 2026, 16:01:33

Site Name
840 - Emirates AuctionsTransaction Number
71803957 (CC10013) (CC10013)

Vehicle Details

Chassis Number	WDDLJ5KB8C*****
Specification	GCC Specification
Make	Mercedes
Model	CLS 350
Model Year	2012
Color	
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY MINOR DENTS, SCRATCHES, PORTION GETTING FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK	دعامية
01.E Trunk	NOT OPEN	صندوق
01.F Fuel Tank	DENT	خزان الوقود
01.G Vehicle Color	GRAY	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY KEY MISSING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	DAMAGED CRACKED	الاطار الامامي
06.B Rear Tyre	DAMAGED CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CUT	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	LEFT SIDE VIEW MIRROR GETTING FADED	المرآيا
10.C AC Condition	NOT CHECKED	المكيف
10.D Dash Board	GETTING FADED PORTION WORN OUT CRACK	لوحة القيادة
10.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae