

Queue Number 2878108

Transaction Date 17 Oct 2026, 11:17:49

Site Name
840 - Emirates AuctionsTransaction Number
14881227 (CC10021) (CC10019)

Vehicle Details

Chassis Number	1C4RJFBG6E*****
Specification	Imported
Make	Jeep
Model	Grand Cherokee
Model Year	2014
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	PORTION DENT,NEED TO REMOVE BOTH SIDE FENDER & UNDER ENGINE COVER FOR PROPER INSPECTION	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED.	دعامية

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA OY / OK	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED PARTS REFITTED MONOR OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	NOT CHECKED PARTS REFITTED MONOR OIL LEAK . PARTS RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

05.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 CRACKED EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX COVER PORTION CRACKED & INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	NOT CHECKED	المكيف
09.C Dash Board	PORTION FADED	لوحة القيادة
09.D Roof Ceiling	PORTION LOOSE	بطانة السقف
09.E Sun Visor	RIGHT SIDE COVER MIRROR DAMAGED.MISSNG	حاجب الشمس
09.F Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae