



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 16 Aug 2022, 12:13:52 |
| Transaction Number | 49064023 (CC10008) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | WP1ZZZ92ZDLA03909 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Porsche |
| Model | Cayenne |
| Model Year | 2013 |
| Color | White |
| Mileage | 298115 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|----------------------------------|--|------------------------|
| 01 Body | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENT,SCRATCHES | الصبغ |
| 01.B Bumper | SCRATCHES | دعامية |
| 01.C Bonnet | SHOCK WEAK | غطاء المحرك |
| 01.D Fenders | FRONT RIGHT SIDE , REAR BOTH SIDE PORTION REPAIRED REPAINTED | مدكار |
| 01.E Doors | RIGHT SIDE BOTH PORTION REPAIRED , REPAINTED | أبواب |
| 02 Transmission Condition | | الجير |
| 02.A Road Test | NOT CHECK | فحص علي الطريق |
| 02.B Visual Gear Box Condition | OIL LEAK .REFITTED. | حالة الجير النظري |
| 03 Interior Condition | | الحاله الداخليه |
| 03.A Power Window Switch | NOT WORKING FROM MAIN SWITCH & LEFT SWITCH MISSING | مفتاح النافذه |
| 03.B Roof Ceiling | LOOSE | بطانه السقف |
| 03.C Door Panel | FRONT RIGHT SIDE LOOSE | لوحة بطانة الباب |
| 04 Suspension System | | ممتص الصدمات |

| DEFECT | REMARKS | |
|------------------------------------|---|--------------------|
| 04.A Arms | LOWER ARM BUSH CRACKED | ازرع |
| 05 Engine Condition | | المحرك |
| 05.A Smoke | BLACK SMOKE | دخان |
| 05.B Visual Engine Condition | REFITTED OIL LEAK & APNORMAL NOISE | حالة المحرك النظرى |
| 06 Tires and Rims Condition | | الاطارات |
| 06.A Rear Tyre | BOTH SIDE 2018 & CRACKED LOW AIR | الاطار الخلفي |
| 06.B Front Tyre | BOTH SIDE 2018 & CRACKED LOW AIR | الاطار الامامي |
| 07 Wipers and Arms | | المساحات |
| 07.A Other | WIPER WATER TANK CAP MISSING | اخرى |
| 08 Chassis Condition | | الشاسي |
| 08.A Chassis | CHASSIS COVERED CHECKED VISIBLE AREA OK | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.