



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>12 Jan 2022, 17:52:11</b>
Transaction Number	<b>34776343 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1FA6P8CF3K5167226</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Ford</b>
Model	<b>Mustang</b>
Model Year	<b>2019</b>
Color	<b>Blue</b>
Mileage	<b>41298 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT BOTH SIDE REPAINTED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED	الصبغ
01.C Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.D Doors	LEFT SIDE REPAINTED,REFITTED	أبواب
01.E Bonnet	REPAINTED,REFITTED	غطاء المحرك
01.F Pillars	LEFT SIDE A/PILLAR POST ,ROCKER PANEL REPAIRED	القوائم
01.G Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Other	ENGINE AIR FILTER MODIFIED	اخرى
02.B Engine Condition	OK	حالة المحرك
<b>03 Seats Condition</b>		<b>المقاعد</b>
03.A Seat Belt	FRONT SIDE NOT WORKING &HAVE EXTRA SEAT BELT	حزام الأمان
03.B Seat Condition	MOUNT MODIFIED	حالة المقاعد
<b>04 Interior Condition</b>		<b>الحالة الداخليه</b>
04.A AC Condition	OK	المكيف

DEFECT	REMARKS	
04.B Other	EXTRA SAFETY BAR FITTING	اخرى
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Spare Tire & Tools	SPARE TIRE & TOOLS MISSING	الاطار الاحتياطي و العدة
05.B Front Tyre	MODIFIED & BOTH SIDE 2020	الاطار الامامي
05.C Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
05.D Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
06.B Other	ALL LIGHT WORKING	اخرى
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Gear Box	OK	الجير
<b>08 Chassis Condition</b>		<b>الشاصي</b>
08.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Suspension Subframe	FRONT & REAR SUB FRAME REFITTED	
<b>10 Battery Condition</b>		<b>حالة البطارية</b>
10.A Battery Condition	OK	حالة البطارية
<b>11 Exhaust System</b>		<b>نظام العادم</b>
11.A Modification	MODIFIED, NOISY	تعديلات
<b>12 Wipers and Arms</b>		<b>المساحات</b>
12.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	--
Chassis No :	1FA6P8CF3K5167226
Vehicle Make :	FORD
Vehicle Model :	MUSTANG
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Blue
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	40637 Kms.
Origin : United States	Model Year : 2019
Gear Type : Manual	Engine Size : 6800 CC
Engine No : NIL	Horse Power : 435
Axles No : 2	Cylinders : 8
No Of Doors : 2	No Of Seats : 4
G. V. W. : 2450 Kgs.	Empty Weight : 1750 Kgs.

Certificate Number :	5-TAS-2021-15692050
Inspection Date :	16-12-2021
Certificate Print Date :	16-12-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Barsha
Total Time Taken :	8 min 0 sec
Appointment Ref Number :	--
Start Time : 17:38	End Time : 17:46
Lane : 05	Token No. : 522
Attempt : 2	Prints No : 1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

8127 KM	837 L	1356 AED	2.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	6800	5000	

## Inspection Remarks:

front both side chassis repaired, ccm ok by work order 2121-12-16-3 and transaction number TRN - 15665361 / remove rear seat supportive frame

## Payment Details

Inspection Performed by 40485 59705 59705	Payment Method Cash	Transaction Number 15692050	Service Fees AED 70 Collected on 16/12/2021
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Emad Ali Mohamed Al Jaghman

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

