



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **16 May 2023, 12:55:25**
 Transaction Number **77438093 (CC10010)** Queue Number **716287**



Chassis Number **MR0CX8CD0J0693502**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Toyota**
 Model **Hilux**
 Model Year **2018**
 Color **White**
 Mileage **399695 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Shock Absorber	WEAK ,LEAK .	ممتص الصدمات
01.B Arms	LOWER ARM BUSHES CRACKED ,	ازرع
02 Body		جسم المركبة
02.A Sign of back accident		وجود مؤشر لحادث في الخلف
02.B Fenders	REAR LEFT SIDE CABIN PANEL REPAIRED ,REPAINTED.	مدكار
02.C Bumper	MISALIGN PORTIOIN DAMAGE ,FRONT CHORME GRILL PORTION DAMAGE .	دعامية
02.D Paint	BODY PORTION REPAIRED,REPAINTED ,DENTS SCRATCHES,	الصبغ
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	OIL LEAK.	حالة الجير النظري
03.B Road Test	NOT CHECKED.	فحص علي الطريق
04 Engine Condition		المحرك
04.A Smoke	WHITE SMOKE.	دخان
04.B Visual Engine Condition	MISFIRING ,ABNORMAL NOISY ,OIL LEAK .	حالة المحرك النظري
05 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
05.A Front Tyre	BOTH SIDE 2021 CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 CRACKED .	الاطار الخلفي
06 Chassis Condition		الشاسي
06.A Chassis	OK & CHASSIS FRAME GETTING RUSTY.	الشاسيه
07 Steering Condition		المقود
07.A Steering Box	OIL LEAK.	جهاز المقود
08 Lights		الاضاءة
08.A Tail Light	LEFT SIDE CRACKED.	الانارة
08.B Warning Light	WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
09 Interior Condition		الحالة الداخليه
09.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.