



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	04 Mar 2023, 11:49:46
Transaction Number	69269584 (CC10013)	Queue Number	682620



Chassis Number	WDCYR48F08X176021
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	G 500
Model Year	2008
Color	White
Mileage	291283 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
02 Seats Condition		المقاعد
02.A Seat Condition	DRIVER SEAT CONER MISSING & RIGHT SIDE COVER LOOSE, PORTION CRACK	حالة المقاعد
03 Interior Condition		الحاله الداخليه
03.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03.B Sunroof	NOT WORKING PROPERLY	فتحت سقف
03.C Power Window Switch	FRONT LEFT SIDE SWITCH LOOSE	مفتاح النافذه
03.D Other	GER LEVRE KNOB WORN OUT , BONNET CABLE INNER HANDLE WORN OUT	اخرى
03.E AC Condition	OK, GRILL PORTION CRACK	المكيف
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
04.C Rims Condition	SCRATCHES	حالة الجنوط

DEFECT	REMARKS	
05 Body		جسم المركبة
05.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES & PORTION RUSTY	الصبغ
05.B Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED & REAR LEFT SIDE PORTION REPAINTED	مدكار
05.C Windshield	FRONT REPLACED	زجاج
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box Mount	MOUNT RUBBER CRACK	كرسي الجير
06.C Propeller Shaft	REFITTED	ناقل الحركة
06.D Visual Gear Box Condition	OIL LEAK , REFITTED, JERKING	حالة الجير النظري
07 Steering Condition		المقود
07.A Other	IDLER ARM BUSH CRACK	اخرى
07.B Steering Box	OIL LEAK DRIPPING	جهاز المقود
08 Engine Condition		المحرك
08.A Smoke	WHITE	دخان
08.B Visual Engine Condition	OIL LEAK , REFITTED	حالة المحرك النظري
08.C Mount	MOUNT RUBBER CRACK	كرسي
09 Exhaust System		نظام العادم
09.A Other	LEAK,REWALDED	اخرى
10 Chassis Condition		الشاسي
10.A Chassis	CHASSIS FRAME RUSTY PROOFED (MUDDY, OILY)	الشاسيه
11 Brake Condition		الفرامل
11.A Disc&Drum	SKIMMING	دسك وطنابير الفرامل
11.B Brake Pedal	SPONGY	دواسة الفرامل
12 Suspension System		ممتص الصدمات
12.A Arms	BUSH CRACK	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	Z 36124 Dubai Private
Chassis No :	WDCYR48F08X176021
Vehicle Make :	MERCEDES
Vehicle Model :	G500
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	291283 Kms.
Origin : Austria	Model Year : 2008
Gear Type : Automatic	Engine Size : 4700 CC
Engine No : 1139623075...	Horse 296
Axles No : 2	Power :
No Of 5	Cylinders : 8
Doors :	No Of Seats : 7
G. V. W. : 2800 Kgs.	Empty 2200 Kgs.
	Weight :

⚠ Retest can be done only in Dubai

Certificate Number :	1-TAS-2023-18987844		
Inspection Date :	09-03-2023		
Certificate Print Date :	09-03-2023		
Services :	Renewal Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	7 min 48 sec		
Appointment Ref Number :	--		
Start Time :	16:14	End Time :	16:22
Lane :	02	Token No. :	241
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle
3 %

Service brake imbalance on rear axle
1 %

Parking brake imbalance between LHS and RHS
9 %

Vehicle on Petrol CO Reading
0 %

Vehicle on Petrol HC Reading
6 PPM VOL

Inspection Findings

Defects	Issue	Severity
Tie-rod, Bushes, Center Link	Excessive wear or defective tie-rod, bushes or link	Major
Gear/Differential repair gear oil leak	Oil leaking continuously	Major
Steering Box	Continuous or excessive oil leak	Major
Engine	Oil leaking continuously	Major

Inspection Remarks: body minor dents&scratches

Payment Details

Inspection Performed by
35063

Payment Method
VTP Credit Account

Transaction Number
18987844

Service Fees
AED 170 Collected on 09/03/2023

Parking Slot No
--

Service Name
Renewal Test

Attempt
1

Received by
Bajurdeen Abdul Gafoor

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لتي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

