CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2971048
Transaction Date	11 Nov 2026, 13:47:26
Site Name	840 - Emirates Auctions
Transaction Number	98451944 (CC10009) (CC10019)



Vehicle Details

Chassis Number	VF3WB5FS4B*******
Specification	GCC Specification
Make	Peugeot
Model	207
Model Year	2011
Color	Black
Mileage	257191 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	LEFT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT	الارضية
01.F Bumper	MISALIGN,PORTION CRACKED	دعامية
01.G Roof	CONVERTIBLE ROOF NOT WORKING	السقف
01.H Bonnet	REPAINTED,PORTION REPAIRED,REFITTED	غطاء المحرك
01.I Trunk	SHOCK NOT WORKING	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OILLEAK REFITTED GETTING RUSTY SHAKING, WIRING OPEN UNSAFE	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	OIL LEAK REFITTED, GETTING RUSTY,	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING PROPERLY	الاضاءة الرئيسية
06.B Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
06.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Steering Oil	MINOR OIL LEAK	زيت المقود
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY	اخري
09.B Mirror	CENTER MIRROR PORTION FADED,LOOSE	المرايا
09.C AC Condition	OK,SWITCH FADED	المكيف
09.D Power Window Switch And Glass	LEFT SIDE NOT WORKING	مفتاح النافذه و الزجاج
09.E Dash Board	GLOVE BOX LOCK DAMAGED	لوحة القياده
09.F Sun Visor	LEFT SIDE COVER MIRROR MISSING	حاجب الشمس
09.G Door Panel	PORTION DAMAGED,LOOSE	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae