CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2870490
Transaction Date	15 Oct 2026, 15:24:02
Site Name	840 - Emirates Auctions
Transaction Number	16327246 (CC10008) (CC10019)

Vehicle Details

Chassis Number	WDD2193751*******
Specification	Imported
Make	Mercedes
Model	CLS 500
Model Year	2007
Color	Silver
Mileage	142336 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	LEFT SIDE BOTH PORTION REPAINTED & REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER BODY FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN.GRILL PORTION DAMAGED	دعامية
01.G Windshield	FRONT DAMAGED	زجاج
01.H Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.I Vehicle Year Model	AS PER VIN DECORDER 2006	سنة صنع المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA /OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	ENGINE DRIVE BELT CRACK	اخري
03.B Engine Visual Condition	MINOR OIL LEAK ,REFITTED ,PARTS GETTIG RUSTY ,SHAKING ,ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT PORTION CUT	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK ,REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Propeller Shaft	FLANGE RUBBER CRACK	ناقل الحركة
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 WORN OUT	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2020 & RIGHT SIDE 2021 EXPIRED CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT,SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
09 Steering Condition		المقود
09.A Axle	BOOT CUT	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	CUP HOLDER CRACK	اخري
10.B Mirror	LEFT SIDE FOLDING NOT WORKING ,CENTER MIRROR COVER DAMAGED	المرايا
10.C AC Condition	OK	المكيف
10.D Roof Light	FRONT LIGHT FRAME PORTION DAMAGED	أنارة السقف
10.E Dash Board	REATHER REPLCED LOOSE , SIDE COVER PORTION CFRACK LOOSE	لوحة القياده
10.F Roof Ceiling	PORTION LOOSE	بطانه السقف
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.