

Queue Number	2822852	Transaction Date	02 Oct 2026, 11:51:17
Site Name	840 - Emirates Auctions	Transaction Number	15040937 (CC10013) (CC10011)



Vehicle Details

Chassis Number	SCBDG4ZG7L*****
Specification	Imported
Make	Bentley
Model	Continental
Model Year	2020
Color	Grey
Mileage	99290 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة	
01.A Fenders	REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED REINFORCEMENT DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAIRED REPAINTED REFITTED, STAY SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	FIBER PAINT NOT CHECK REFITTED,LOGO GETTING FADED	صندوق
01.I Door Handle &Lock	LEFT SIDE HANDLE LOCK COVER MISSING	مقابض الأبواب والأقفال
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME BOTH SIDE OUTER SUPPORT BRACKETS REPAIREDFRONT BUMPER FRAME BULK HEAD FENDER FRAME BOTH SIDE OUTER SUPPORT BRACKETS REPAIRED	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition		الشاسي
02.A Chassis	FRONT RIGHT SIDE CHASSIS LOWER EDGE MINOR DENT / CHASSIS COVERED	الشاسيه

03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED	الحالة النظرية للمحرك

04 Seats Condition	المقاعد
--------------------	---------

Condition	Remarks	الحالة
04.A Seat Condition	FRONT RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY , COVER PORTION HOLE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES / FRONT INNER REPAIRED	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Suspension Subframe	REFITTED	اخرى
07.B Other	SUSPENSION PARTS REFITTED	
08 Interior Condition		الحالة الداخليه
08.A Other	CENTER CONSOLE PANEL & REAR CUP HOLDER PANEL WORN OUT / INTERIOR PARTS MINOR GETTING RUSTY	اخرى
08.B AC Condition	OK, GRILL PORTION LOOSE	المكيف
08.C Dash Board	LEATHER ,PORTION LOOSE	لوحة القيادة
08.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	SWITCH ADJUSTMENT LOOSE	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae