CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2890903
Transaction Date	21 Oct 2026, 14:35:50
Site Name	840 - Emirates Auctions
Transaction Number	51057083 (CC10013) (CC10011)



Vehicle Details

Chassis Number	MHKMF5BF3K*******
Specification	GCC Specification
Make	Toyota
Model	Avanza
Model Year	2019
Color	White
Mileage	128350 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED PORTION DENT	الارضية
01.E Bumper	MISALIGN SCRATCHES,PART MISSING	دعامية
01.F Windshield	COWL PANEL COVER PORTION LOOSE,PART MISSING	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD REPAIRED ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED PORTION RUSTY BULGED CRACK OPEN DETACHED / REAR BOTH LOWER EDGE DENT	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED , MUDDY DIRTY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Belt	LEFT SIDE WORN OUT	حزام الأمان
04.B Seat Condition	FRONT EXTRA COVER,REAR SEATS MISSING	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY , MUDDY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07 Lights		**الاضاءة**
07.A Head Light	RIGHT SIDE LENS FADED,LEFT GETTING FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION CRACKED	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		**الفرامل**
08.A Brake Pedal	SPONGY WEAK	دواسة الفرامل
09 Interior Condition		**الحاله الداخليه**
09.A Other	REAR CIGARETTE LIGHTER MISSING / INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
09.B AC Condition	OK	المكيف
09.C FLoor Matting	PORTION DAMAGED LOOSE	فرش الأرضيه
09.D Audio	STEREO PANEL PORTION WORN OUT,ANTENNA DAMAGED	صوتيات
09.E Roof Ceiling	DIRTY,EXTRA FITTING,FRONT RIGHT SIDE GRAB HANDLE MISSING	بطانه السقف
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae