



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **18 Apr 2025, 15:39:25**
 Transaction Number **43484220 (CC10021) (CC10021)** Queue Number **1449198**



Chassis Number **5GRGN23U46H111136**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Hummer**
 Model **H2**
 Model Year **2006**
 Color **Grey**
 Mileage **N/A NA**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION FADED	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Windshield	FRONT CRACK	زجاج
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS RUST PROOFED, PORTION DENT, BODY MOUNT BEND, GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED, PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED, PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

DEFECT	REMARKS	
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX LOOSE,INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT CHECK	المكيف
10.C Roof Ceiling	PORTION CRACK,DAMAGED	بطانة السقف
10.D Door Panel	PORTION LOOSE,PORTION DAMAGED	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.
- For complaints and inquiries reach out to us on wecare@carscheck.ae



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.
- للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae