



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	21 Jun 2022, 13:20:23
Transaction Number	94184357 (CC10008)	Queue Number	312309



Chassis Number	JN6AE54S49X016251
Engine Number	
Vehicle Class	Heavy
Manufacturer	Nissan
Model	Urvan
Model Year	2009
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Engine Condition		
		المحرك
01.A Visual Engine Condition	ENIGNE NOT START ALL SYSTEM NOT CHECK , OIL WET & REFITTED	حالة المحرك النظري
01.B Mount	MOUNT BUSH CRACKED	كرسي
02 Transmission Condition		
		الجير
02.A Visual Gear Box Condition	NOT CHECK , OPEN & REFITTED , BOLT DAMAGED	حالة الجير النظري
02.B Road Test	NOT CHECK	فحص علي الطريق
03 Interior Condition		
		الحاله الداخليه
03.A AC Condition	NOT CHECK	المكيف
03.B Sun Visor	LEFT SIDE MISSING , RIGHT SIDE LOOSE	حاجب الشمس
03.C Odometer reading	NOT CHECK	قراءة عداد المسافات
03.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
04 Steering Condition		
		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05 Tires and Rims Condition		
		الاطارات

DEFECT	REMARKS	
05.A Rear Tyre	BOTH SIDE 2018/2021 CRACKED	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2020 CRACKED	الاطار الامامي
05.C Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
05.D Rims Condition	FRONT LEFT SIDE & REAR RIGHT SIDE 2 WHEEL NUT MISSING	حالة الجنوط
06 Suspension System		ممتص الصدمات
06.A Suspension Subframe	FRONT SUBFRAME 1 BOLT LOOSE	
06.B Leaf Spring	BUSH CRACKED	
06.C Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
06.D Other	STABILIZER LINK BOOT CUT	اخرى
07 Body		جسم المركبة
07.A Rusty	UNDER BODY PARTS & SUSPENTION,CHASSIS RUSTY & FLOOR RUSTY HOLE	صدأ
07.B Windshield	FRONT WINDSHIELD CRACKED	زجاج
07.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION RUSTY	الصبغ
07.D Other	REAR BACK PANEL DENT	اخرى
07.E Fuel Tank	DENT	خزان الوقود
08 Chassis Condition		الشاسي
08.A Chassis	OK	الشاسيه
09 Exhaust System		نظام العادم
09.A Other	EXHAUST PIPE REWELDED	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.