



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 Mar 2023, 12:07:53
Transaction Number	81038820 (CC10010)	Queue Number	685982



Chassis Number	SALGA2BV6JA380966
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Vogue SE
Model Year	2018
Color	Blue
Mileage	23559 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		الاطارات
01.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
<b>02 Transmission Condition</b>		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OK	حالة الجير النظري
<b>03 Interior Condition</b>		الحاله الداخليه
03.A Roof Ceiling	PORTION LOOSE	بطانه السقف
03.B AC Condition	OK	المكيف
<b>04 Engine Condition</b>		المحرك
04.A Visual Engine Condition		حالة المحرك النظري
<b>05 Chassis Condition</b>		الشاسيه
05.A Chassis	CHASSIS FULLY COVERED ,CHECKED ONLY VISIBLE AREA OK.	الشاسيه
<b>06 Body</b>		جسم المركبة

DEFECT	REMARKS	
06.A Fenders	REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	مدكار
06.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
06.C Doors	REAR RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
06.D Bonnet	PORTION REPAINTED,	غطاء المحرك
06.E Floor	UNDER BODY FULLY COVERED ,CHECKED ONLY VISIBLE AREA.	الارضية

07 Suspension System

ممتص الصدمات

07.A Other	SUSPENSION PARTS REFITTED.	اخرى
------------	----------------------------	------

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.