CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899692
Transaction Date	29 Oct 2026, 13:45:24
Site Name	840 - Emirates Auctions
Transaction Number	36227046 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JTHBE5C24C*******
Specification	Imported
Make	Lexus
Model	IS 350
Model Year	2012
Color	Black
Mileage	175872 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE & REAR LEFT SIDE REPAINTED PORTION REPAIRED & FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Bonnet	FULLY STICKER PROTECTED PAINT NO CHECK	غطاء المحرك
01.F Trunk	REPAINTED PORTION REPAIRED , MISALIGN	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	MUFFLER CUT REWELDED	تعديلات
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2024 & RIGHT SIDE 2023 CRACK	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES CUT	ازرع
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT , INETRIOR PARTS GETTING RUSTY ,	اخري
11.B AC Condition	OK	المكيف
11.C Dash Board	PORTION WORN OUT	لوحة القياده
11.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae