



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	03 Jun 2022, 12:12:40
Transaction Number	23163913 (CC10006)	Queue Number	312309



Chassis Number	WVWAP2AN3DE524533
Engine Number	
Vehicle Class	Car
Manufacturer	Volkswagen
Model	Passat
Model Year	2013
Color	Brown
Mileage	125139 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
02 Interior Condition		الحاله الداخليه
02.A AC Condition	OK	المكيف
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظرى
03.B Road Test	NOT CHECK	فحص علي الطريق
04 Chassis Condition		الشاصي
04.A Chassis	VISABLE AREA OK	الشاسيه
05 Engine Condition		المحرك
05.A Other	ENGINE START BUTTON DAMAGED & NOT WORKING PROPERLY	اخرى
05.B Visual Engine Condition	OIL LEAK , REFITTED	حالة المحرك النظرى
05.C Mount	MOUNT BUSH CRACKED	كرسي
06 Body		جسم المركبة

DEFECT	REMARKS	
06.A Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
06.B Fenders	FRONT BOTH SIDE & REAR LEFT SIDE REPAINTED,PORTION REPAIRED	مدكار
06.C Floor	UNDER BODY COVERD	الارضية
06.D Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.