



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 16 Aug 2022, 13:19:18 |
| Transaction Number | 33600215 (CC10008) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | MM7DE3HY7EW278188 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Mazda |
| Model | 2 |
| Model Year | 2014 |
| Color | White |
| Mileage | 119605 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|--------------------------|---------------------|
| 01 Tires and Rims Condition | | الاطارات |
| 01.A Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 01.B Front Tyre | BOTH SIDE 2020 | الاطار الامامي |
| 02 Engine Condition | | المحرك |
| 02.A Visual Engine Condition | MINOR OIL LEAK | حالة المحرك النظري |
| 02.B Mount | MOUNT RUBBER CRACKED | كرسي |
| 03 Transmission Condition | | الجير |
| 03.A Visual Gear Box Condition | SIGN OF MINOR OIL LEAK | حالة الجير النظري |
| 03.B Gear Box Mount | MOUNT RUBBER CRACKED | كرسي الجير |
| 03.C Road Test | NOT CHECK | فحص علي الطريق |
| 04 Suspension System | | ممتص الصدمات |
| 04.A Arms | LOWER ARM BUSHES CRACKED | ازرع |
| 04.B Ball Joint | BOOT CUT | مفصل كروي |
| 05 Steering Condition | | المقود |
| 05.A Tie Rod End | BOOT CUT | مؤخرة الرودادات |

| DEFECT | REMARKS | |
|------------------------------|---|----------------------------|
| 06 Interior Condition | | الحاله الداخليه |
| 06.A Power Window Switch | FRONT BOTH SIDE NOT WORKING | مفتاح النافذه |
| 06.B Mirror | VIEW MIRROR LOOSE | المرايا |
| 06.C AC Condition | OK&CENTER GRILL BROKEN | المكيف |
| 07 Lights | | الاضاءة |
| 07.A Head Light | LENS FADED | الاضاءة الرئيسية |
| 08 Seats Condition | | المقاعد |
| 08.A Seat Condition | SEATS HAVE EXTRA COVER | حالة المقاعد |
| 09 Body | | جسم المركبة |
| 09.A Fenders | RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED | مدكار |
| 09.B Doors | FRONT RIGHT SIDE REPAINTED | أبواب |
| 09.C Paint | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES | الصبغ |
| 09.D Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 09.E Other | FRONT BUMPER FRAME BULK HEAD REFITTED | اخرى |
| 10 Chassis Condition | | الشاصي |
| 10.A Chassis | CHECKED VISIBLE AREA OK | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.