CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941690
Transaction Date	04 Nov 2026, 14:27:24
Site Name	840 - Emirates Auctions
Transaction Number	63658665 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1G1BE5SM7K*******
Specification	Imported
Make	Chevrolet
Model	Cruze
Model Year	2019
Color	Silver
Mileage	190334 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR PORTION DENT	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED,FADED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATORSUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED, RIGHT SIDE CRASH BOX KINK	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED SLIGHTLY BEND/ LEFT SIDE CVERED	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	SHAKING PARTS REFITTED GETTING RUSTY OIL WET/ SIGN OF OVER HEAT	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	DELAY SHIFTTING PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 CRACKED EXPIRED	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	OK	المكيف
08.C Air Bag	DAMAGED	وسائد هوائية
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	KNOB WORN OUT MELTED	ذراع نقل السرعات
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae