



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 17:54:50
Transaction Number	86312503 (CC10006)	Queue Number	312309



Chassis Number	1GTN29E04CZ337431
Engine Number	
Vehicle Class	Car
Manufacturer	GMC
Model	Sierra
Model Year	2012
Color	Black
Mileage	170552 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Dash Board	CRACKED	لوحة القيادة
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C AC Condition	OK	المكيف
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
03 Engine Condition		المحرك
03.A Visual Engine Condition	OIL WET	حالة المحرك النظري
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	OK	حالة الجير النظري
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Body		جسم المركبة
05.A Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING RUSTY	صدأ

DEFECT	REMARKS	
05.B Pillars	RIGHT SIDE DOOR PILLAR REPAIRED	القوائم
05.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
05.D Sign of side accident		وجود مؤشر لحادث في الجانب
06 Brake Condition		الفرامل
06.A Disc&Drum	REAR LEAK	دسك وطنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	OIL LEAK	ممتص الصدمات
07.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
07.C Arms	LOWER ARM BUSHES CRACKED	ازرع
08 Chassis Condition		الشاسي
08.A Chassis	FRONT BOTH SIDE CHASSI END,RIGHT SIDE BODY MOUNT DENT & CHASSIS FRAME COMPLETELY RUSTY, PORTION RUST PROOFED	الشاسيه
09 Lights		الاضاءة
09.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	66346983
Chassis No :	1GTN29E04CZ337431
Vehicle Make :	GMC
Vehicle Model :	SIERRA
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Black
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	170554 Kms.
Origin : United States	Model Year : 2012
Gear Type : Automatic	Engine Size : 6600 CC
Engine No : NONE	Horse 255
Axles No : 2	Power :
No Of 2	Cylinders : 8
Doors :	No Of Seats : 3
G. V. W. : 2950 Kgs.	Empty 2200 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17389312		
Inspection Date :	11-08-2022		
Certificate Print Date :	11-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	24 min 7 sec		
Appointment Ref Number :	--		
Start Time :	12:11	End Time :	12:35
Lane :	01	Token No. :	138
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
9 %	10 %	5 %	0.72 %
Vehicle on Petrol HC Reading			
165 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Fuel tank and pipings repair or change petrol tank leak	Leaking	Major
Warning triangle warning triangle not found	Missing	Major
Tinted remove front wind shield long tinted	Dark	Major
Rear registration plate lamps fix plate lamp missing	Missing	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	6600	6200	

Inspection Remarks:

FRONT BOTH SIDE CHASSIS END MINOR DENT / FRONT & REAR BUMPER / BULKHEAD / FENDER REPAIRED / CHASSIS MINOR RUSTY / FRONT LEFT SIDE TIRE / MINOR SIDE WALL WORN

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104	VTP Credit Account	17389312	AED 170 Collected on 11/08/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

